

EPA Notification of Hazardous Waste Site

TXS-000-001-280 000-57

United States
Environmental Protection
Agency
Washington, DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

RECEIVED
JUN 11 1981

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Marathon Oil Company (Houston Division Onshore Operations)

Street P. O. Box 3128

City Houston

State TX

Zip Code 77001

TXD 00182 9563

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Phoenix Lake Gas Plant

Street P. O. Box 426

City Orange

County Orange

State TX

Zip Code 77630

hasit TX8818

Childress Rd

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Miller, Michael, Environmental Engineer

Phone 713/629-6600

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1965

To (Year) 1972

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

- 1. ☐ Organics
- 2. ☐ Inorganics
- 3. ☐ Solvents
- 4. ☐ Pesticides
- 5. ☐ Heavy metals
- 6. ☐ Acids
- 7. ☐ Bases
- 8. ☐ PCBs
- 9. ☐ Mixed Municipal Waste
- 10. ☐ Unknown
- 11. ☐ Other (Specify) _____

Source of Waste:
Place an X in the appropriate boxes.

- 1. ☐ Mining
- 2. ☐ Construction
- 3. ☐ Textiles
- 4. ☐ Fertilizer
- 5. ☐ Paper/Printing
- 6. ☐ Leather Tanning
- 7. ☐ Iron/Steel Foundry
- 8. ☐ Chemical, General
- 9. ☐ Plating/Polishing
- 10. ☐ Military/Ammunition
- 11. ☐ Electrical Conductors
- 12. ☐ Transformers
- 13. ☐ Utility Companies
- 14. ☐ Sanitary Refuse
- 15. ☐ Photofinish
- 16. ☐ Lab. Hospital
- 17. ☐ Unknown
- 18. ☐ Other (Specify) _____

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:
EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

D 007	*		

*See I MARATHON OIL CO PHOENIX

LAKE GAS PLANT
TXD 001 829 563
SUPERFUND
FILE

NOV 1992

REORGANIZED

22158

Federal Register / Vol. 46, No. 72 / Wednesday, April 15, 1981 / Notices

Notification of Hazardous Waste Site	Side Two	
F Waste Quantity Place an X in the appropriate boxes to indicate the facility types found at the site. In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons. In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.	Facility Type 1 <input type="checkbox"/> Piles 2 <input type="checkbox"/> Land Treatment 3 <input type="checkbox"/> Landfill 4 <input type="checkbox"/> Tanks 5 <input type="checkbox"/> Impoundment 6 <input type="checkbox"/> Underground Injection 7 <input type="checkbox"/> Drums, Above Ground 8 <input type="checkbox"/> Drums, Below Ground 9 <input checked="" type="checkbox"/> Other (Specify) <u>Surface Discharge</u>	Total Facility Waste Amount <u>None Present</u> Total Facility Area <u>Not Applicable</u>

G Known, Suspected or Likely Releases to the Environment:
Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment. ☒ Known ☐ Suspected ☐ Likely ☐ None

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

Cooling tower blowdown water containing chromates was discharged from this natural gas processing plant. No hazardous wastes are known to remain. It is estimated that 1260 gallons per day of water with a chromium concentration of 15-30 ppm were discharged.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name C. L. Roberts
Street P. O. Box 3128
City Houston State TX Zip Code 77001
Signature C L Roberts Date 6/12/81
☐ Owner, Present
☐ Owner, Past
☐ Transporter
☐ Operator, Present
☒ Operator, Past
☐ Other